U.S. ENVIRONMENTAL PROTECTION AGENCY REGION II, REMOVAL ACTION BRANCH POLLUTION REPORT

HEADING THE THE THE TENT (EDE) I HEADING DE SHIP OLIDINATE

November 16, 1999

Eric J. Wilson, On-Scene-Coordinator

U.S. EPA, Region II, Removal Action Branch

J. Rotola, EPA R. Salkie, EPA G. Zachos, EPA T. Johnson, EPA P. Mannino, EPA C. Petersen, EPA M. Olsen, EPA M. Sundram, EPA D. Karlen, EPA P. Seppi, EPA R. Cahill, EPA B. Bellow, EPA D. Kraft, EPA B. Dease, EPA R. Byrnes, EPA OIG T. Mignone, ATSDR

J. Pasqualo, NJDHSS J. Smolenski, NJDEP START J. Corica, South Plainfield

Records Center

Cornell-Dubilier Electronics Site, Residential Cleanup

South Plainfield, Middlesex County, New Jersey

POLREP: 13

BACKGROUND A handsday dom and sold sold and another as self-

Site No: GZ 0017 Delivery Order No.: CERCLA Response Authority:

NJD981557879 CERCLIS No .: Final NPL market Nood was of NPL Status:

NJDEP and NJDHSS Notified State Notification: Status of Action Memorandum: Approved September 19, 1998

Start Date RV2: March 29, 1998

Completion Date RV2: On-going March 15, 1999 Start Date BB2: September 16, 1999 Completion Date B2:

Start Date BB3: September 23, 1999

Completion Date BB3: On-going depins acost . s. 1 cett vitte lan

III. SITE INFORMATION

The site is located in a mixed industrial, commercial and residential area of South Plainfield, New Jersey and consists of the Hamilton Industrial Park, adjacent contaminated residential and commercial properties and

contaminated portions of the Bound Brook downstream of the industrial park. Cornell-Dubilier Electronics operated at the industrial park from 1936 to 1962 and allegedly disposed of polychlorinated biphenyl (PCB) contaminated materials and other hazardous substances directly onto site soils. PCBs have been detected in soils and in building interiors at the industrial park, at adjacent residential and commercial properties and in the surface water and sediment of the Bound Brook.

In March 1997 EPA ordered the owner of the industrial park to take actions to stabilize the site. These actions included the installation of drainage controls to limit the movement of contaminants to the nearby Bound Brook through surface water run off; paving of driveways and parking areas in the industrial park to limit the generation and off-site migration of contaminated dust; and installation of a security fence to restrict access to contaminated areas, and prevent the tracking of contaminants into the surrounding community.

The second secon

IV. RESPONSE INFORMATION and the second of second and the second of t

Current Situation

The situation at the site has not changed significantly since the last report.

Removal activities (through 11/13/99)

tors a management of the second of the secon

Tier 2 Residential Soil Removal (BB2) No work took place between Monday, November 8 and Friday, · November 12.

On Saturday November 13, minor property restorations were made at Property U (207 Delmore), Property X (115 Delmore), Property BB (511 Hamilton), Property CC (119 Delmore), and Property DD (229 Delmore). Additional restoration activities are scheduled for the week of November 15. Disposal of the remaining waste generated as a result of the removal activities (i.e. decontamination water and personal protective equipment) is tentatively scheduled for the week of November 15. Barrio at to the second of the second of

...', '1...

Other Site Activities

On October 8, EPA notified the owner of the industrial park, DSC of Newark, Inc. that additional removal actions are necessary to stabilize the site and protect public health, welfare or the environment. The following actions are required: characterize, remove and dispose of accumulated waste stored in the area formerly operated as a driving school; establish vegetative cover in unvegetated, unpaved areas of the industrial park; and repair and maintain drainage controls down gradient of unvegetated, unpaved areas until permanent vegetative is established. Plans for this work, due October 23, have not been received.

On October 28, EPA notified DSC that they are in violation of the Unilateral Administrative Order (UAO) issued to them for site stabilization actions. To date DSC has not the taken action necessary to come into compliance with the UAO.

B. Planned Removal Activities

A PRP-lead removal action is underway at 7 Tier 2 residential properties. Interior cleaning is planned at 2 Tier 1 and 2 Tier 2 properties upon completion of the Tier 2 soil removal. As discussed in the previous section, additional removal activities are required to stabilize the site.

C. Next steps

The restoration of Tier 2 properties will continue. The Disposal of the remaining waste generated as a result of Tier 2 residential Decontamination water will be disposed of.

D. Key Issues

None.

V... COST INFORMATION (Fund-Lead Removal Actions through 11/13/99)

** * * * .	. Amount	Cost	Amount
. •	Budgeted	To Date	Remaining
ERRS Costs.	\$ 332,000	179,646	152,354
START Costs	\$ 22,000	6,989	15,01ì
Contingency	21,000	n/a	21,000
EPA Costs	\$ 50,000	36,750	13.250
Total Costs	\$ 425,000	\$ 223,385	\$ 201,615
- Control of the cont	The second secon	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	Contract Con

The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery. VI. DISPOSITION OF WASTES

Waste stream	Medium	Quantity	Treatment	Disposal
Decontamination Solids (RV2)	Soil/Solids	4 drums	TSCA Landfill	CWM, Model City,
Decontamination Liquids (RV2)	Liquids ''	5 drums	Incineration	CWM, Model City,
Non-TSCA Regulated Soil (BB2)	Soil .	1744 tons	Landfill	G.R.O.W.S. Morrisville, PA
TSCA Regulated Soil (BB2)	Soil	22 tons	Landfill	CWM, Model City, NY
Non-TSCA Regulated Soil (BB3)	Soil	777 tons	Landfill	G.R.O.W.S. Morrisville, PA
TSCA Regulated Soil (BB3)	Soil	43 tons	Landfill	CWM, Model City,